

Selection Chart

	Page	Electric Screwdriver				Controller/Counter	
		Series	Model	Features	Starting Method	Model	Voltage
	5-6	7400A	DLV7410A/7410HA/7420A	Bit Grounding Low Shock ESD		DLC1110	100/115/220/ 230/240 V AC
			DLV7419A/7419HA/7429A	Bit Grounding Low Shock ESD Clean Room			
	7	5700	DLV5720/5720H/5740 DLV5740H/5750	Bit Grounding Low Shock ESD		DLC0350 DLC0950	100/115/230 V AC
	8	5800	DLV5820/5820H/5840	Bit Grounding ESD	Lever Start	DLC0350 DLC0250E	100 V AC
	9	7300	DLV7313/7323/7333	Low Voltage		DLC1213A	100/115/ 230/240 V AC
			DLV7325/7335	Clean Room			
	10	7300 -BME/ BKE	DLV7321-B □ E DLV7331-B □ E	ESD		DLC1213A- □ □ B	100/115/ 230/240 V AC
			DLV7319/7329/7339/7349-BME	Clean Room Low Shock ESD			

	11	7000	DLV7020/7030/7031	Transformerless	Lever Start		100/115 V AC
		8000	DLV8020/8030/8031		Push to Start		
	12	7104	DLV7124/7134/7144	Transformerless	Lever Start		230 V AC
		8104	DLV8124/8134/8144		Push to Start		
		8204	DLV8154	Transformerless High Torque	Push to Start		
			DLV8224/8234/8244	Transformerless High Speed			

	13-14	7500	DLV7530/7540 DLV7550	Torque Reach Light High Torque	Lever Start	DLC4511-GGB DLR1510-JE	230 V AC
		8500	DLV8530/8540 DLV8550	Torque Reach Light High Torque	Push to Start		

	15	7100	DLV7120/7130/7140 DLV7221	Transformerless High Speed	Lever Start		115 V AC
		7200	DLV7231/7241 DLV7251	Transformerless High Torque			
		8100	DLV8120/8130/8140 DLV8150	Transformerless High Torque	Push to Start		
		8200	DLV8221 DLV8231/8241	Transformerless High Speed			
			DLV8251	Transformerless High Torque			

	17	02/12/16	DLV02/12/16	Brushless Motor ESD(BKE)	Lever Start	DLC16S-W □ B	100 - 240 V AC
--	----	----------	-------------	-----------------------------	-------------	--------------	----------------

	18	A (30A/45A/70A)	DLV30A06L/30A12L/30A20L DLV30A06P/30A12P/30A20P	Transformerless Brushless Motor	Lever Start		230 V AC
			DLV45A06L/45A12L DLV45A06P/45A12P		Push to Start		
			DLV70A06L		Lever Start		
			DLV70A06P		Push to Start		
					Lever Start		

	19	30/45/70-IKE	DLV30LL/30SL/30HL-IKE DLV30LP/30SP/30HP-IKE	Low Voltage Brushless Motor	Lever Start	DLR70S-WGB DLC70S-WGB	100 - 240 V AC
			DLV45LL/45SL-IKE DLV45LP/45SP-IKE		Push to Start		
			DLV70LL-IKE		Lever Start		
			DLV70LP-IKE		Push to Start		
					Lever Start		

	22	3300 (for Automation) 3100 (for Automation)	DLV3321/3331 DLV3121/3131/3141/3151	For Automation	External Input	DLC3310	24 V AC 100 V AC
--	----	--	--	----------------	----------------	---------	---------------------

	23-24	A (for Automation) (30A/45A/70A)	DLV30A □ A - □ (AA)J DLV45A □ A - □ (AA)K DLV70A06A - □ (AA)K	Brushless Motor For Automation	External Input Signal		100 V AC
--	-------	-------------------------------------	---	-----------------------------------	--------------------------	--	----------

Selection Chart

■ This chart is for reference only.

