

27th August, 2012

To our valued distributor

Issue on Selfer Hydraulic Pump HPD-05

Since 1st July, 2006, we have supplied the machine tool products to be complied with the RoHS directive, but have found that the vinyl cord (ground wire) and the Suction Filter for the Selfer Hydraulic Pump “HPD-05” were not.

We herewith report to you, and apologize for any inconvenience caused on this matter.

We kindly ask you for repair of the applicable products sold in the past and also the ones in your current stock.

Regarding the repair fees, we will bear it at our end. Further details will follow separately.

Best regards,

Atsushi Shirai

Executive Director, Engineering

Object Products and serial numbers:

HPD-05 110V-120V CE
Produced Jun. 2006 ~ Dec. 2011 75 units
0700183 ~ 0700188
0700332 ~ 0700335
0700349 ~ 0700354
0800024 ~ 0800027
0800051 ~ 0800056
0800114 ~ 0800121
0800167 ~ 0800171
0800202 ~ 0800211
0800262 ~ 0800276
0800338 ~ 0800342
0800378 ~ 0800387
0800393 ~ 0800397
0000041 ~ 0000050
0000086 ~ 0000095
0100027 ~ 0100029

HPD-05 220V-240V CE
Produced Jun. 2006 ~ Dec. 2011 107 units
0600146 ~ 0600150
0700050 ~ 0700057
0700189 ~ 0700192
0700330 ~ 0700331
0700346 ~ 0700348
0800028 ~ 0800030
0800122 ~ 0800131
0800172 ~ 0800176
0800212 ~ 0800216
0800241 ~ 0800250
0800277 ~ 0800281
0800368 ~ 0800377
0000071 ~ 0000075

Contact address:

NITTO KOHKI EUROPE CO., LTD.

Unit 21, The Empire Centre, Imperial Way, Watford Hertfordshire,
WD24 4TS, United Kingdom

TEL : +44-1923-239668

NITTO KOHKI DEUTSCHLAND GMBH

Lerchenstrasse 47, D-71144 Steinenbronn, Germany

TEL : +49-7157-22436