

27<sup>th</sup> August, 2012

### Issue on Delvo series DLV81□3, DLV71□3

Since 1st July, 2006, we have supplied the Delvo products to be complied with the RoHS directive, but have found that some of the parts of the Delvo series DLV81□3 and DLV71□3 were not.

We herewith report to you, and apologize for any inconvenience caused on this matter.

We will replace the applicable parts to RoHS compliant parts, so kindly contact below address for further details.

RoHS non-compliant part	Object model
TORQUE ADJUSTMENT RING COVER	DLV8133-MKG, DLV8143-MKG DLV7133-MKG, DLV7143-MKG
FRAME HANDLE	DLV8133-MKG, DLV8143-MKG

#### Object Products and serial numbers

DLV8133-MKG
Produced Jul. 2006 ~ Sep. 2008 1,435 units
0671781 ~ 0671880
0681531 ~ 0681680
0691161 ~ 0691260
0691701 ~ 0691800
06X1031 ~ 06X1080
06Y1031 ~ 06Y1130
06Z0831 ~ 06Z0930
0711021 ~ 0711120
0720781 ~ 0720880
0750091 ~ 0750192
0750691 ~ 0750709
0760471 ~ 0760570
0770001 ~ 0770100
0815101 ~ 0815110
0851931 ~ 0852035
0865051 ~ 0865077
0870451 ~ 0870472
0891801 ~ 0891850

DLV8143-MKG
Produced Jul. 2006 ~ Feb. 2010 427 units
0670001 ~ 0670050
0750321 ~ 0750370
0750711 ~ 0750728
07Z0741 ~ 07Z0840
0821311 ~ 0821320
0840461 ~ 0840500
0870473 ~ 0870481
0890321 ~ 0890420
1020591 ~ 1020640
DLV7133-MKG
Produced Jul. 2006 ~ Oct. 2006 140 units
0671881 ~ 0671970
06X1081 ~ 06X1130
DLV7143-MKG
Produced Jul. 2006 ~ Jul. 2008 200 units
0670051 ~ 0670100
06X1251 ~ 06X1300
0852041 ~ 0852140
0861581 ~ 0861600
0870482 ~ 0870511

Contact address :

NITTO KOHKI OVERSEAS BUSINESS DIV  
 TEL: +81-3-3755-9545  
 FAX: +81-3-3753-8791  
 E-mail: overseas@nitto-kohki.co.jp