

27<sup>th</sup> August, 2012

## To our valued customers using Super Cupla

Since 1st July, 2006, we have supplied the coupler products (except Lever Lock Cupla) to be complied with the RoHS directive, but have found that the amount of lead (Pb) contained in the base material of the aluminum alloy for the “Super Cupla” models “01SN”, “02SN” and “02SMF”, and “Super Cupla(With Tube Fitter)” models “02SC-6”, “02SC-8”, “02SCL-6”, “02SCL-8”, “02SCB-6” and “02SCB-8”, exceeds the allowed limits of the directive.

We herewith report to you, and apologize for any inconvenience caused on this matter.

There will be no effect on the performance of the products that you are using now.

We will continue to sell the under mentioned applicable models as items exempt from the RoHS directive. However, if the applicable models will be installed into electrical and electronic equipment for export to the European Union, kindly note that appropriate measures per corresponding regulation should be necessary.

Should you have any further questions, please contact below address for details.

### ■The Object 9 models of the Super Cupla series



[01SN][02SN]



[02SMF]



[02SC-6][02SC-8]



[02SCL-6][02SCL-8]



[02SCB-6][02SCB-8]

### ■Contact for this matter

Overseas Division, Nitto Kohki Co., Ltd.

9-4, Nakaikegami 2-Chome, Ohta-ku, Tokyo, 146-8555

Tel: +81-3-3755-9954

E-mail: overseas@nitto-kohki.co.jp

Working hours: 9:00~17:00 (Except for Saturday, Sunday and Japanese national holidays)

\* RoHS directive: European directive for Restriction of the use of certain Hazardous Substances in electrical and electronic equipment.